



Quote

From:

Norm Electrical Engineering

23 Park View Road

N17 9AT

Tottenham/Haringey

London

02082458400

07724308998

info@normelectric.co.uk

Quote Number	2591
Quote Date	13/07/2026
Valid Until	19/07/2026
Total	£1,495.40

To:

Bridgebourne Property Services

124-128 City Road

London, EC1V 2NX

020 8103 9427

<https://www.bridgebourne.co.uk/>

nal@bridgebourne.co.uk

Carry out the remedial works identified during the Electrical Installation Condition Reports (EICRs) to rectify C1, C2 and FI observations, where applicable. The works include the supply and installation of replacement electrical accessories and components, testing of the completed works, and the issue of the appropriate certification where required. All remedial works will be completed in accordance with **BS 7671 (18th Edition)**.

Thanks for choosing Norm Electrical Engineering | info@normelectric.co.uk Hope to work together on this projects .

Hrs/Qty	Service	Rate/Price	Adjust	Sub Total
1	Taylor Close 1, 2, 3, 4, 5, 6 (Flats 37 & 38) – EICR Remedial Works (Labour Only) Labour only to carry out the remedial works identified during the Electrical Installation Condition Report (EICR) for Taylor Close 1, 2, 3, 4, 5, 6 (Flats 37 & 38). This includes the installation of replacement electrical accessories/components supplied separately, testing of the completed remedial works, and verification that the installation complies with the applicable requirements of BS 7671 (18th Edition).	£125.00	0%	£125.00
2	Materials – EICR Remedial Works (Taylor Close 1-6, Flats 37 & 38) Supply of materials for EICR remedial works, including 2 × Wylex RCBOs and 1 × consumer unit blanking plate (fuse box hole closer).	£19.20	0%	£38.40
1	EICR Certificate Re-Issue – Taylor Close 1, 2, 3, 4, 5, 6 (Flats 37 & 38) Re-inspection and testing of the completed remedial works, verification that the installation complies with BS 7671 (18th Edition), and re-issue of the Electrical Installation Condition Report (EICR) for Taylor Close 1, 2, 3, 4, 5, 6 (Flats 37 & 38) following satisfactory completion of the remedial works.	£65.00	0%	£65.00

Thanks for choosing [Norm Electrical Engineering](mailto:info@normelectric.co.uk) | info@normelectric.co.uk Hope to work together on this projects .

Hrs/Qty	Service	Rate/Price	Adjust	Sub Total
1	Taylor Close-7,8,9,10,11,12-39,40- – EICR Remedial Works (Labour Only) Labour only to carry out the remedial works identified during the Electrical Installation Condition Report (EICR) for Taylor Close . This includes the installation of replacement electrical accessories/components supplied separately, testing of the completed remedial works, and verification that the installation complies with the applicable requirements of BS 7671 (18th Edition).	£125.00	0%	£125.00
2	Materials – EICR Remedial Works (Taylor Close 7,8,9,10,11,12-39,40- Supply of materials for EICR remedial works, including 2 x Wylex RCBOs and 1 x	£19.00	0%	£38.00
1	EICR Certificate Re-Issue – Taylor Close Taylor Close-7,8,9,10,11,12-39,40- Re-inspection and testing of the completed remedial works, verification that the installation complies with BS 7671 (18th Edition), and re-issue of the Electrical Installation Condition Report (EICR) for Taylor Close following satisfactory completion of the remedial works.	£65.00	0%	£65.00
1	Taylor Close-13,14,15,16,17,18-41,42 – EICR Remedial Works (Labour Only) Labour only to carry out the remedial works identified during the Electrical Installation Condition Report (EICR) for Taylor Close 1, 2, 3, 4, 5, 6 (Flats 37 & 38). This includes the installation of replacement electrical accessories/components supplied separately, testing of the completed remedial works, and verification that the installation complies with the applicable requirements of BS 7671 (18th Edition).	£170.00	0%	£170.00

Thanks for choosing [Norm Electrical Engineering](http://normelectric.co.uk) | info@normelectric.co.uk Hope to work together on this projects .

Hrs/Qty	Service	Rate/Price	Adjust	Sub Total
2	Materials – EICR Remedial Works (Taylor Close 13,14,15,16,17,18-41,42) Supply of materials for EICR remedial works, including 2 × Wylex RCBOs and required to safely isolate the damaged entrance garden light fittings, including 2 × IP-rated junction boxes and 2 sets of WAGO connectors. Wiska One Gel Cartridge	£32.00	0%	£64.00
1	EICR Certificate Re-Issue – Taylor Close 13,14,15,16,17,18-41,42 Re-inspection and testing of the completed remedial works, verification that the installation complies with BS 7671 (18th Edition), and re-issue of the Electrical Installation Condition Report (EICR) for Taylor Close following satisfactory completion of the remedial works.	£65.00	0%	£65.00
1	Taylor Close-19,20,21,22,23,24-43 – EICR Remedial Works (Labour Only) Labour only to carry out the remedial works identified during the Electrical Installation Condition Report (EICR) for Taylor Close 1, 2, 3, 4, 5, 6 (Flats 37 & 38). This includes the installation of replacement electrical accessories/components supplied separately, testing of the completed remedial works, and verification that the installation complies with the applicable requirements of BS 7671 (18th Edition).	£125.00	0%	£125.00
2	Materials – EICR Remedial Works (Taylor Close-19,20,21,22,23,24-43) Supply of materials for EICR remedial works, including 2 × Wylex RCBOs	£19.00	0%	£38.00

Thanks for choosing [Norm Electrical Engineering](mailto:info@normelectric.co.uk) | info@normelectric.co.uk Hope to work together on this projects .

Hrs/Qty	Service	Rate/Price	Adjust	Sub Total
1	EICR Certificate Re-Issue – Taylor Close-19,20,21,22,23,24-43 Re-inspection and testing of the completed remedial works, verification that the installation complies with BS 7671 (18th Edition), and re-issue of the Electrical Installation Condition Report (EICR) for Taylor Close following satisfactory completion of the remedial works.	£65.00	0%	£65.00
1	Taylor Close-25,26,27,28,29,30-44 – EICR Remedial Works (Labour Only) Labour only to carry out the remedial works identified during the Electrical Installation Condition Report (EICR) for Taylor Close. This includes the installation of replacement electrical accessories/components supplied separately, testing of the completed remedial works, and verification that the installation complies with the applicable requirements of BS 7671 (18th Edition).	£125.00	0%	£125.00
2	Materials – EICR Remedial Works (Taylor Close-25,26,27,28,29,30-44 Supply of materials for EICR remedial works, including 2 x Wylex RCBOs and required to safely isolate the damaged entrance garden light fittings, including 3 x IP-rated junction boxes and 2 sets of WAGO connectors. Wiska One Gel Cartridge	£34.00	0%	£68.00
1	EICR Certificate Re-Issue – Taylor Close-25,26,27,28,29,30-44 Re-inspection and testing of the completed remedial works, verification that the installation complies with BS 7671 (18th Edition), and re-issue of the Electrical Installation Condition Report (EICR) for Taylor Close following satisfactory completion of the remedial works.	£65.00	0%	£65.00

Thanks for choosing [Norm Electrical Engineering](http://normelectric.co.uk) | info@normelectric.co.uk Hope to work together on this projects .

Hrs/Qty	Service	Rate/Price	Adjust	Sub Total
1	Taylor Close-31,32,33,34,35,36-45- EICR Remedial Works (Labour Only) Labour only to carry out the remedial works identified during the Electrical Installation Condition Report (EICR) for Taylor Close. This includes the installation of replacement electrical accessories/components supplied separately, testing of the completed remedial works, and verification that the installation complies with the applicable requirements of BS 7671 (18th Edition).	£125.00	0%	£125.00
2	Materials - EICR Remedial Works (Taylor Close-31,32,33,34,35,36-45) Supply of materials for EICR remedial works, including 2 x Wylex RCBOs and required to safely isolate the damaged entrance garden light fittings, including 3 x IP-rated junction boxes and 2 sets of WAGO connectors. Wiska One Gel Cartridge	£32.00	0%	£64.00
1	EICR Certificate Re-Issue - Taylor Close-31,32,33,34,35,36-45 Re-inspection and testing of the completed remedial works, verification that the installation complies with BS 7671 (18th Edition), and re-issue of the Electrical Installation Condition Report (EICR) for Taylor Close following satisfactory completion of the remedial works.	£65.00	0.00%	£65.00

Sub Total	£1,495.40
Tax	£0.00
Total	£1,495.40

Thanks for choosing [Norm Electrical Engineering](http://normelectric.co.uk) | info@normelectric.co.uk Hope to work together on this projects .



This is a fixed price quote. If accepted, we require a 50% deposit upfront before work commences. If there is no other agreements. [Terms & Conditions](#)
