

From:

[Norm Electrical Engineering](#)

23 Park View Road

N17 9AT

Tottenham/Haringey

London

02082458400

07724308998

info@normelectric.co.uk

Invoice Number	2609
Invoice Date	21/04/2026
Due Date	30/04/2026
Total Due	£0.00

To:

Palvinder kainth

N176DH 52

+44 7890 423083

Palvinderkainthxxxx@gmail.com

Extractor Fan Fault Finding & Replacement – Bathroom

Hrs/Qty	Service	Rate/Price	Adjust	Sub Total
1	Extractor Fan Fault Finding – Bathroom Carried out fault finding on bathroom extractor fan to identify cause of malfunction. Electrical testing and inspection completed to diagnose issue.	£99.00	0%	£99.00
1	Extractor Fan Replacement – Bathroom Removal of faulty extractor fan and supply & installation of new unit. Included installation materials such as cables and Wago connectors. Final testing carried out to ensure safe and correct operation.	£120.00	0.00%	£120.00

Thanks for choosing [Norm Electrical Engineering](#) | info@normelectric.co.uk Thanks for choosing
Norm Electrical Engineering Hope to work on next projects .



Invoice

Sub Total	£219.00
Tax	£0.00
Discount	-£129.00
Paid	-£90.00
Total Due	£0.00

Norm Electrical Engineering
Bank :Lloyds
Sort Code : 30-99-50
Account Number :89187160

Payment Terms: Payment due within 30 days. Late payments may incur statutory interest and recovery costs.Full
Terms & Conditions: [Terms & Conditions](#)

Thanks for choosing [Norm Electrical Engineering](#) | info@normelectric.co.uk Thanks for choosing
Norm Electrical Engineering Hope to work on next projects .